



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A. San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 5/26/17

San Diego Unified School District  
**Silver Gate Elementary**

| Sample ID | Sample Date | Sample Time | Source   | External ID   | Lead | Units |
|-----------|-------------|-------------|----------|---------------|------|-------|
| W1172872  | 05/18/17    | 06:08 AM    | SAMPLE 1 | 3710020-BIG-A | < 5  | ug/L  |
| W1172873  | 05/18/17    | 06:06 AM    | SAMPLE 2 | 3710020-BIG-B | < 5  | ug/L  |
| W1172874  | 05/18/17    | 06:03 AM    | SAMPLE 3 | 3710020-BIG-C | < 5  | ug/L  |
| W1172875  | 05/18/17    | 06:15 AM    | SAMPLE 4 | 3710020-BIG-D | < 5  | ug/L  |
| W1172876  | 05/18/17    | 06:12 AM    | SAMPLE 5 | 3710020-BIG-E | < 5  | ug/L  |

**Source**      **Source Description**

- SAMPLE 1    Cafeteria, Wall mounted interior (East of the Room) Sink/faucet facing Dining Area, between Kitchen & conference CC2, bubbler on right side of tile sink basin
- SAMPLE 2    building #1, Wall mounted exterior (North of Bldg), facing Lunch Arbor, two single bubbler fountains, upper right fountain
- SAMPLE 3    building #1, Wall mounted exterior (West of Bldg), between Storage Rm & Corridor, facing blacktop, triple bubbler fountain, left bubbler
- SAMPLE 4    building #3, Wall mounted exterior (South of Bldg), between Custodian Locker Rm & Girls' RR, facing blacktop/playground, triple bubbler fountain, left bubbler
- SAMPLE 5    building #2, Wall mounted exterior (East of Bldg), between Storage Rm & Corridor, facing Library Bldg, triple bubbler fountain, right bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist