



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A, San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 6/7/17

San Diego Unified School District
University City High

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1172899	05/19/17	06:19 AM	SAMPLE 1	3710020-BJC-A	< 5	ug/L
W1172900	05/19/17	06:08 AM	SAMPLE 2	3710020-BJC-B	< 5	ug/L
W1172901	05/19/17	06:16 AM	SAMPLE 3	3710020-BJC-C	< 5	ug/L
W1172902	05/19/17	06:11 AM	SAMPLE 4	3710020-BJC-D	5.38	ug/L
W1172903	05/19/17	06:07 AM	SAMPLE 5	3710020-BJC-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 200 Bldg, Interior hallway between Men & Women's RR, Around the corner from 208, dual bubbler fountain, right bubbler
- SAMPLE 2 Outdoor Food Service Kiosk, West wall and around the corner from cold lunch line, dual bubbler fountain, right bubbler
- SAMPLE 3 400 Bldg, Interior hallway next to room 458, dual bubbler fountain, left bubbler
- SAMPLE 4 Arts Tech bldg, South exterior wall (back side of room 231), dual bubbler fountain, left bubbler
- SAMPLE 5 Kitchen, East interior wall, faucet above two compartment sink

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Doug Campbell, Senior Chemist