



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A. San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 4/18/17

San Diego Unified School District  
**Zamarano Elementary**

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1165247	04/08/17	08:40 AM	SAMPLE 1	3710020-ACI-A	< 5	ug/L
W1165248	04/08/17	08:43 AM	SAMPLE 2	3710020-ACI-B	< 5	ug/L
W1165249	04/08/17	08:46 AM	SAMPLE 3	3710020-ACI-C	< 5	ug/L
W1165250	04/08/17	08:35 AM	SAMPLE 4	3710020-ACI-D	< 5	ug/L
W1165251	04/08/17	08:50 AM	SAMPLE 5	3710020-ACI-E	< 5	ug/L

**Source**      **Source Description**

- SAMPLE 1    Bldg 700 South Campus, Kindergarden Room 730 Sink Bubbler
- SAMPLE 2    Bldg 700 South Campus, 1st Floor between Girl's and Boy's restrooms facing playground, dual fountain right bubbler
- SAMPLE 3    1st Grade Room South Campus, Between Girl's and Boy's restrooms facing playground, left single fountain bubbler
- SAMPLE 4    1st Grade Room South Campus, next to Supply Room, left single fixture bubbler
- SAMPLE 5    Restrooms North Campus, next to Girl's restroom facing lunch arbor, dual fountain right bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Tom Burger, Associate Chemist